






Type  
**Assessment Report**

Scan date 10.08.2022 16:38  
Timeframe 16:40 - 16:47

Registration no  
**333DCJ**

Quality  
**Low quality**

VIN code  
**VR3F35GFRKY120370**

Image	Timestamp	Location	Feedback
 VIN	16:40	<a href="#">View location</a>	VIN code mismatch (KL1JF68E9CK517229)
 Front driver side	16:44	<a href="#">View location</a>	Image was taken 264 seconds later than the previous oneClean 99% Registration number mismatch (695BPG)
 Back driver side	16:45	<a href="#">View location</a>	Clean 100% Registration number mismatch (695BPG)
 Back passenger side	16:46	<a href="#">View location</a>	Clean 100% Registration number mismatch (695BPG)
 Front passenger side	16:47	<a href="#">View location</a>	Clean 100% Registration number mismatch (695BPG)

Type  
**Damage Report**


Scan date  
10.08.2022 16:38

Timeframe  
16:40 - 16:47

Registration no  
**333DCJ**

VIN code  
VR3F35GFRKY120370

● Damage



Type	Side	Body part	Image
Dent	Front	Front bumper	<a href="#">View image</a>
Paint damage	Front left	Mirror	<a href="#">View image</a>
Paint damage	Front	Hood	<a href="#">View image</a>
Paint damage	Front	Hood	<a href="#">View image</a>
Paint damage	Front	Front bumper	<a href="#">View image</a>
Paint damage	Front	Front bumper	<a href="#">View image</a>
Paint damage	Back	Rear bumper	<a href="#">View image</a>

Paint damage	Back	Rear bumper	<a href="#">View image</a>
Paint damage	Back	Rear bumper	<a href="#">View image</a>
Paint damage	Back	Rear bumper	<a href="#">View image</a>
Paint damage	Right	Body	<a href="#">View image</a>
Rust	Left	Fender	<a href="#">View image</a>
Scrape	Back	Rear bumper	<a href="#">View image</a>
Scrape	Back	Rear bumper	<a href="#">View image</a>
Scratch	Back	Rear bumper	<a href="#">View image</a>
Crack	Front	Front bumper	<a href="#">View image</a>
Other damage	Front	Front bumper	<a href="#">View image</a>
Other damage	Back	Rear bumper	<a href="#">View image</a>

Type  
**Damage Report**

Image type  
**Front left**



1



Fender  
Rust

2



Mirror  
Paint damage

3



Front bumper  
Other damage

4



Front bumper  
Paint damage

5



Front bumper  
Dent



Type  
**Damage Report**

Image type  
**Back left**



1



Rear bumper  
Other damage

2



Rear bumper  
Paint damage

3



Rear bumper  
Paint damage

4



Rear bumper  
Paint damage

5



Rear bumper  
Paint damage



Type  
**Damage Report**

Image type  
**Back right**



1



Rear bumper  
Other damage

2



Rear bumper  
Scrape

3



Rear bumper  
Scrape

4



Rear bumper  
Paint damage

5



Rear bumper  
Paint damage

6



Rear bumper  
Paint damage

1



Rear bumper  
Scratch

2



Body  
Paint damage



Type  
**Damage Report**

Image type  
**Front right**




1



Hood  
Paint damage

2



Hood  
Paint damage

3



Front bumper  
Other damage

4




Front bumper  
Paint damage

5



Front bumper  
Dent

6



Front bumper  
Crack



1



Front bumper  
Paint damage