

Type
Damage Report

Registration no
268MRC


Damages
Yes

Scan date
25.03.2024 16:46

Timeframe
16:47 - 16:48

VIN code
TMB1CCNE4H0139206

Decision
Repair



Type	Body part	Image
Chip	Windshield	View image



Front side

Reference image

AI COMMENTS

No AI comments.

COMMENTS

No additional comments.



Windshield from outside

Reference image

AI COMMENTS

No AI comments.

COMMENTS

No additional comments.



1 Chip
Windshield

AI COMMENTS

- Repair

COMMENTS

No additional comments.